

Examination of CPM[®] MagnaCut Blade Failed During Manufacture at Bark River

Requested by Bob Shabala
Niagara Specialty Metals

Report by: Gary Maddock

View of fractured blade as received for analysis

(blade exhibits primary ground bevel with unfinished edge)




Close up of fracture:

- Blade surface is clean
- Fracture extends from jimping notch across blade in perpendicular fashion
- No evidence of mechanical damage on blade
- Macro hardness checks:
 - Blade- HRC 62.5-63
 - Handle- HRC 62.5-63




Specimen sectioned, mounted, and polished




Composite view of fracture surface fracture.

- Fracture surface is smooth and continuous
- There is no evidence of oxidation, prior cracking, or other discontinuities
- Failure is indicative of bending load applied to flat side of blade



Macro view of corner:


- Rough surface evident within jimping notch
- Smooth fracture surface
- Bottom edge likely crack initiation site



General Microstructure

1000X Vilella's Etch

- Uniform dispersion of very fine carbide as expected for CPM MagnaCut Alloy
- No evidence of material defects
- Appears properly hardened and tempered



Transverse view at surface
along primary ground bevel.
1000X Vilella's Etch

- Uniform structure along edge
- No evidence of thermal damage



Transverse view of unfinished
cutting edge
50X Vilella's Etch


- Surface integrity appears very good
- Consistent microhardness found along
blade edge and cross section:
745-779 HV (=RC 61.9-63.2)



View looking down at edge of crack face


1000X Vilella's Etch

- Fracture appears transgranular in nature with minimal plastic deformation
- Microstructure appears normal along crack face
- Limited ductility evident in fracture behavior is typical given the alloy content and hardness of the blade material



View looking down on jimping
notch/crack intersection
100X Vilella's Etch

- Rough surface noted in jimping
- No evidence of thermal damage



Higher mag view of jimping notch/crack intersection

500X Vilella's Etch

- Rough surface in jimping may have accentuated (stress riser) notch effect
- Microstructure appears normal under surface

